

Insertion thermometer



- Digital thermometer
- LCD display
- Temperature range: -50°C ~ + 150°C
- Insertion depth of stainless steel probe: approx. 110 mm
- Measurement accuracy:
 - +/- 1°C within range of -50°C to + 100°C
 - +/- 2°C within range of -100°C to + 200°C
- Battery: 1 x 1,5V
- Dimensions: Ø 35.5 mm x 138.7 mm (H)

A293.043

Turn on thermometer, insert into food product and read the temperature as measured.

Wash thermometer by hand. Do not submerge the button. Remove tough grease stains with a brush or delicate steel wool.

ATTENTION: do not leave the thermometer in the food product while cooking. Do not subject the thermometer to extreme differences in temperature.

The H/T button is for saving temperature measurements. The temperature will be saved in the thermometer by pressing and holding the button. By quickly pressing and releasing the button the saved value will be displayed on the thermometer.

Bartscher GmbH
Franz-Kleine-Str. 28
D-33154 Salzkotten
Germany

phone: +49 (0) 5258 971-0
fax: +49 (0) 5258 971-120