


AT1001



300079V

Original-Gebrauchsanleitung V1/0718


PRODUCT DESCRIPTION

Name	Tray trolley AT1001
Code-No.:	300079V
Material:	Aluminium, plastic
Model:	 Designed for: Fast-food trays Serving trays Area of application: Clearing Tray holders Drawers: Format: 370 x 570 mm / 356 x 456 mm Number: 10 Distance between the trays: 120 mm Load-bearing capacity per drawer, max.: 5 kg Total load-bearing capacity, max.: 50 kg Can be loaded from both sides Castors: 4 swivel castors, 2 with break Diameter castors: 125 mm State at delivery: assembled for ready to use Side walls can be written on with standard whiteboard markers.
Dimensions:	W 470 x D 685 x H 1596 mm
Weight:	25 kg

We reserve the right to implement the technical modifications!

Bartscher

List of parts



- 1 Frame
- 2 Side wall (2x)
- 3 Tray holders (10x)
- 4 Swivel castors without brake (2x)
- **5** Swivel castors with brake (2x)



Accessories (not included in the delivery!)

Glasses basket AT1000

Material: stainless steel Dimensions: W 385 x D 645 x H 75 mm Weight: 2.75 kg Code-No.: 300179



Drip tray AT1000

Material: stainless steel Dimensions: W 435 x D 645 x H 25 mm Weight: 1.25 kg **Code-No.: 300279**



User instructions

- Unpack the clearing trolley and accessories and check the delivery for completeness. Remove and dispose of all packaging material according to the environmental protection regulations.
- Remove protective film from the clearing trolley.



- Fix the castors to the side elements by screwing them into the frame corner posts (left figure).
- Place the clearing trolley on the castors and check its stability.

- The clearing trolley can be loaded from both sides. Place appropriate trays onto the tray holders (see section "**Product description**")
- After placing the trolley in a required location secure it with use of the castor brakes, preventing unintended displacement.





 Write on the side walls according to requirements with standard whiteboard markers (not included in the delivery!).

Cleaning instructions

• Clean the clearing trolley with a soft, moistened cloth. **Never** use harsh or coarse cleaning agents which may scratch the surface of the clearing trolley. Finally, dry thoroughly all cleaned surfaces.

Bartscher GmbH Franz-Kleine-Str. 28 33154 Salzkotten Germany phone: +49 5258 971-0 fax: +49 5258 971-120 **Service-Hotline:** +49 5258 971-197 www.bartscher.com