

**Freezer / fridge thermometer****Temperature range: -30 °C ~ + 50 °C****Display: Ø approx. 44 mm****A292.049**

For use in freezers and fridges, in dry storage and for measurement of external and internal temperatures.

Tape at the rear of the thermometer can be used to mount it. The thermometer can also be hanged up using the hook at its front.

**IMPORTANT:** The thermometer cannot be used for measuring temperatures in baking ovens. It is not designed for measuring high temperatures.

Bartscher GmbH  
Franz-Kleine-Str. 28  
D-33154 Salzkotten  
Germany

phone: +49 (0) 5258 971-0  
fax: +49 (0) 5258 971-120